		۵			C]				٥	I		٥		C		Ø				1	٥											C	J					O		C		;	Ţ	≥		
5727	ر المعالمات. Call (408) 945-772 م ب7 مد (408) 2 45-772 م	Adaptec maintain of the with another 232XD controller.	Swap the drive with many regood drive.	Replace the cable in its order and ity again:	if none of the accession of the problem, then swap out components কেন্দ্রী গাঁৱসথ cure the problem, then swap	power requireme. With the drive vendor for the correct drive	are correct. Consume aesure that the +5V and +12V voltages	required by the driver supply can support the added current	Check that the name of a condition on each drive is set properly.	Check that the turking encors: or Read/Write errors:		Check to see that the set is a set of and CMOS DAM show	Won't boot to C:	manufacturer. We is ESDI certified. Check with the drive	Make sure the caller tails to format	Check that the conversion of the correctly set.		use soft sectoring, for propersettings of these jumpers. Do not	your drive vendor that also for hard or soft sectoring. Consult	for "bytes per sectimpers for number of sectors per track" and	ESDI drives have jectoriates	incorrect drive by hand 44 should be used.	being used, only acted to Pin 1 of the drive. If only one drive is	Controller is connected incerto drives. Be sure that Pin 1 on the	Check hord drive the state 33 coles to Drive 0. J2 does to	that it is correctly provide the type of the junctions drive, be such that it is correctly provide the type of cable you are using.	Check the drive south and the bard disk drive be sure	Recal error, or northing into ally collinectors.	16 twisted between the two in the two properties in the twisted between the two properties in two properties in the two properties i	the twisted cable wells being used, only the last connector on	drive. If only one driftle controller is connected to Pin 1 of the	sure that Pin 1 on test be sure J5 goes to both floppy drives. Be	Check floppy cable poor in A (ACB-2322D only):		the system will book and the formy raive. Then you can proceed	to allow this re-trying hospital been formalied yet. You will have	drive even though 15 13 and 50 retry booting to the hard	Some PC AI systems	Long boot time:	continue.			JTING CHECKLIST	OUBLESHOC 23272			
6	adaptec, 691 soc		please contact y in	Will you reserve to the information or other technical support.	notice. Adaptec rearing without notification to its users, without reservation w	Jicie is for information only and issubject to change without The material in this are where the right to make changes in the product design	CHANGES	Authorization (TRMA is a contract of the contr	has either been reputyer must request and obtain a Return Material	subjected to misuse. Since original working period or any provisions do not expliced or replaced by Seller. Prior to returning any	repaired or altered the science, or accident. The aforementioned	ANY OTHER LIABILITIE's apply to any of such products which shall have been this warroot, shall not except by the Seller, or which shall have been	OTHER OBLIGATION STATES AND CHILD WITH THE SALE OF THE SAID ARTICLES.	AFREASED, STATUTU OR LIABILITIES ON THE SELLER'S PART, AND IT NEITHER	defective. THIS WARNERS FOR A PARTICULAR PURPOSE, AND OF ALL	returned to the Selles a usual of the Series and Content was a series and the Selles and Series and the Selles and Series and S	an its sole option, to see the sole of the	normal use and serv [®] (ec)dacing or (ii) repairing or (iii) giving credit tor, any at its solo action to 1 shawithin five (5) years from date of shipment, be	The Seller warrants total income and a solution of the seller's obligations under this Warranty are the inited.	FIVE . We then that the products to be delivered under this	ENCENTRAL CIMILED LIFE-TIME WARKANTY		Milpitas, California 9'	by any means, electric distriction adapted, inc., by notatinative and a second	may be reproduced within bosont of Adopted Ind. Additional Bud	© Copyright 1989 by UsiQiaries, Inc. Altrights teserved, two part of this publication of Copyright 1989 by UsiQiaries, Inc. Altrights teserved, two part of this publication of the second system, or transmitted, in any form of			available from the $U_{4}^{0.25}$	Haw to Heartify and S. Government Printing Office, Washington, D.C. 20402.	booklet prepared by Section Pontio-TV Interference Problems." This booklet is	If necessary, the using diditional suggestions. The user may tind the tollowing	receiver are on differenced radio/	Plug the computer that alarnch clicuits.	Relocate the complete and the receiver.	Depring traceiving Aller with respect to the receiver.	one or more of the factors	radio or television reduces encouraged to try to correct the interference by	residential installation which can be determined by turning the equip- occur in a particular reprifor, which can be determined by turning the equip-	are designed to provide atton. If this equilibrium to be cause interference will not	tested and found to asceptitications in "subpart J or Part I sorr FUC knies", which accordance with the ider easonable protection against such interference in a	used properly, that is וושי וי ונמו שישיאטורו הבשטונות. וויונג עביו ויא עביי ויאס may cause interfere לקימיטיע with the limits for a Class B computing device in	This equipment gene in strict accordance with the manufacturers instructions.		FIC.C. CERTIFICATION		



*Note: If you are using DOS and yc more than 1024 cylinders, select operating system enable 63-sector translation. G OpWAT: or SPEED- then install your operating system size noise and size of the sector translation of the sector translation. With the sector the sector translation of the sector translati	 Boot to DOS, and run DEBUG. Tripe in : A > DEBUG < CR>-G=C800:5 < CR> The Adaptec format menu will Choose: 1 - to primary-formatic Choose: 1 - to primary-formatic The controller will read the num cylinders from the drive. The more assolved in. Now just keep hitting <cr>. (to be read in.</cr> After format is complete. Chocurs for the defaults). software. Go to DOS FDISK and struct in end this storm and the second drive. 	QUICK INSTALLATION 1. Install controller and drives into cable them together. Run a flo both floppy drives (ACB-2322D on the END of the cable goes to hard drive cable from J4 and c drives. Connect one 20-pin cat2/9ar PC AT and the first hard drive, and from J2:29% cable from J5 to enwy. The connector drive (If installed).
$\begin{bmatrix} DRIVE 1 & DRIVE 0 \\ 1 & 1 & 1 \\ 2 & 3 & 4 \\ 5 & 6 \\ 7 & J^7 & 0 \\ 0 & MICROCODE \\ 2/128 & 0 \\ 1 & J_{13} & 0 \\ 1 & J_{13} & 0 \\ 0 & T & T & T \\ 0 & T & T $	adaptec, inc. ACB-2320/22D	
PERS CONNECTORS J5 - FLOPPY DRIVE J3 - HARD DRIVE 0. DATA CABLE J2 - HARD DRIVE 1. DATA CABLE J2 - HARD DRIVE CONTROL CABLE J4 - HARD DRIVE CONTROL CABLE J1 - DRIVE ACTIVITY LIGHT ro two * = as shipped Out = No jumper installed In = Jumper installed If = d	JUMPERS J10-1 HARD DISK PORT ADDRESS *Out = 1F0-1F7 In = 170-177 J10-2 FLOPPY DISK PORT ADDRESS *Out = 3F0-3F7 In = 370-377 J10-3 FLOPPY DISK DISABLE *Out = Floppy enabled In = Floppy disabled J11-1 FLOPPY DIVE SPEED *Out = Single speed In = Dual speed J12 BIOS ADDRESS 1 2 3 *C8000 out out out CC000 in out out D0000 out in out D0000 out in out D0000 out in out D13 *1-2 IRQ 14 2-3 IRQ 15	SOFTWARE OPTION JUN J7-1 NOT USED J7-2 LOGICAL DRIVE SPL "Out = drive uses ph parameters in = Drive 0 is split in logical drives, (if over 1024 cylinde J7-3 RESERVED J7-4 NOT USED J7-5 READ AHEAD CACH "Out = Enabled In = No Read Ahead performed. J7-6 RESERVED J7-7 RESERVED