

# **RELEASE NOTES**

**HP IP Console Switch Firmware Release**  
**part numbers 262585-B21 (1×1×16), 262586-B21 (3×1×16)**  
**Release date 4-2-2005**

## **Main Firmware**

Application firmware version 3.0.1

## **Interface Adapter Firmware**

PS2 IA : 3.0.5

USB IA : 2.0.3

Serial IA: 1.0.1

## **Change Report**

1. Issue fixed: Loss of video sync when an unpowered Interface Adapter is connected to the KVM switch. The IA is not powered when the server it is connected to is powered off or when the IA is connected to the KVM switch but not connected to a server.
2. Issue fixed: PS2 Interface Adapter update to fix keymap issue with Mode 1 server interface. Interface Adapter must be upgraded after first flashing the IP Console Switch firmware to version 3.0.1.