November 2001 15XM-1101A-WWEN

Prepared by: ABG Marketing Communications

Compaq Computer Corporation

Contents

Introduction	3
Windows 95 "Patch"	3
Windows 95 Drivers	4

Configuring Compaq *Evo* Computers for Microsoft Windows 95

Abstract: This guide describes the procedures and files required to configure Compaq EvoTM computer systems to function with the MicrosoftTM WindowsTM 95 Operating System.

Notice

This publication does not constitute an endorsement of the product or products that were tested. The configuration or configurations tested or described may or may not be the only available solution. This test is not a determination of product quality or correctness, nor does it ensure compliance with any federal, state or local requirements.

Compaq, the Compaq logo, Compaq Insight Manager, and Evo are trademarks of Compaq Information Technologies Group, L.P. in the U.S. and other countries.

Microsoft and Windows are trademarks of Microsoft Corporation in the U.S. and other countries

Pentium is a trademark of Intel Corporation in the U.S. and other countries.

Other product names mentioned herein may be trademarks and/or registered trademarks of their respective companies.

Compaq shall not be liable for technical or editorial errors or omissions contained herein. The information in this document is provided "as is" without warranty of any kind and is subject to change without notice. The warranties for Compaq products are set forth in the express limited warranty statements accompanying such products. Nothing herein should be construed as constituting an additional warranty.

©2001 Compaq Computer Corporation.

Configuring Compaq Evo Computers for Microsoft Windows 95 White Paper prepared by ABG Marketing Communications

First Edition (November 2001) Document Number 15XM-1101A-WWEN

Introduction

Compaq does not officially support Microsoft Windows 95 Operating System (Windows 95) in Compaq *Evo* products; however, Compaq recognizes that some customers have custom or proprietary software images based upon Windows 95. As a result, Compaq provides this document to assist customers who wish to purchase *Evo* systems and continue to deploy their Windows 95-based software.

This paper describes the procedures and files required to allow *Evo* computer systems to function with Windows 95. To acquire Windows 95 support, you will need to download one "patch" from the Microsoft website and a number of Softpaqs from the Compaq support websites provided in this document.

Windows 95 "Patch"

At the time Windows 95 was released, processor speeds were much slower than they are today. Windows 95 has some "speed sensitive" code in the operating system that causes lockups with faster processors, which was first noted with the AMD K6 processor. The software patch identified as the "AMD K6 Patch" allows Windows 95 to function correctly on systems with faster processors, including those found on *Evo* platforms.

Note: This Windows 95 patch is not AMD processor specific. It merely reflects the name of the first processor with which Microsoft noted the issue. For specific information about this patch, refer to Microsoft Knowledge Base Article Q192841 available at: http://support.microsoft.com/support/kb/articles/Q192/8/41.ASP?LN=EN-US&SD=gn&FR=0&qry=Q192841&rnk=1&src=DHCS_MSPSS_gn_SRCH&SPR=W95

Compaq discovered that the procedures outlined in the Knowledge Base article could not be followed on some platforms, including *Evo*, because the affected platform could not start Windows 95 in safe mode. Therefore, the Windows 95 patch could not be run.

For such cases, use this alternate procedure:

1. Download AMDK6upd.exe from Microsoft to a bootable floppy disk. The .exe file can be found at:

http://www.microsoft.com/windows95/downloads/contents/WURecommended/S_WUServic ePacks/AMDPatch/Default.asp

 Extract the files from AMDK6upd.exe to the floppy by executing AMDK6upd.exe /T:a:\ /C.

Document the switches by entering AMDK6upd.exe /?.

- 3. Start the Windows 95 installation following the normal procedures.
- 4. When the error occurs (which should be on first actual boot into Windows 95) or the machine simply does not start Windows 95, boot the machine using the bootable floppy created in Step 1.
- 5. Manually copy the updated driver files on the diskette to their proper locations. A batch file can be created to perform this task if it will be repeated numerous times. Copy each of the following files into these locations:

scsiport.pdr—Copy to C:\Windows\System\IOSubsys. disktsd.vxd—Copy to C:\Windows\System\IOSubsys. esdi_506.pdr—Copy to C:\Windows\System\IOSubsys. hsflop.pdr—Copy to C:\Windows\System\IOSubsys. cdfs.vxd—Copy to C:\Windows\System\VMM32. ios.vxd—Copy to C:\Windows\System\VMM32. int13.vxd—Copy to C:\Windows\System\VMM32.

If the version of Windows 95 is OSR2.1 or OSR2.5: *ntkern.vxd*—Copy to C:\Windows\System\VMM32.

Note: These paths assume that Windows 95 is being installed to C:\Windows. If a custom path was chosen for the Windows 95 installation, you will need to change the paths above to reflect the appropriate subdirectory.

- 6. Remove the floppy and reboot system. If prompted, select Normal Startup of Windows 95.
- 7. Complete the Windows 95 installation procedure.
- 8. To properly register the update within the Windows 95 registry, you will need to run the AMDK6upd.exe [without any command switches] from within Windows 95.

Windows 95 Drivers

To run the *Evo* systems with Windows 95, download and install the following drivers available at:

http://www.compaq.com/support/files/index.html http://www.compaq.com/support/files/allsp.html http://www.compaq.com/support/files/desktops/us/download/10795.html http://www.compaq.com/support/files/desktops/us/download/10828.html

- Intel NIC driver—for all Evo Systems: SP18756
- ADI Audio driver—for all Evo Systems: SP18530
- Chipset INF driver—for all Evo Systems: SP18071
- NVidia Graphics driver—for *Evo* systems using Intel Pentium 4 processors and NVidia Graphics: SP18540
- Intel Video Graphics driver—for Evo systems using Celeron processors: SP16519
- 3Com NIC driver—for all Evo Systems [with a 3Com NIC installed]: SP18954