

## Smart Array 6i version 2.74

This Smart Array firmware will recommend updates for some SCSI disk drive models during the POST routine after the Smart Array firmware has been installed. It is suggested that disk drive firmware updates be completed before updating the Smart Array firmware.

Disk drive firmware components are available from:

[http://h18000.www1.hp.com/support/files/storage/us/locOsCat/99\\_56.html](http://h18000.www1.hp.com/support/files/storage/us/locOsCat/99_56.html)

A later version of the disk drive firmware may be available and should be used.

Disk Drive Model	Minimum Firmware	Disk Drive Family
BB009135B4	B021	SCSI 9GB 7200 WU2
BB009235B6	B021	SCSI 9GB 7200 WU2
BB018135B5	B021	SCSI 18GB 7200 WU2
BB018235B7	B021	SCSI 18GB 7200 WU2
BD004153C3	B415	SCSI 4GB 10K WU2
BD004253C4	B415	SCSI 4GB 10K WU2
BD00962A66	B008	SCSI 9GB 10K WU3
BD0096349A	3B12	SCSI 9GB 10K WU3
BD009635C3	B022	SCSI 9GB 10K WU3
BD00965333	B915	SCSI 9GB 10K WU3
BD00972A69	B008	SCSI 9GB 10K WU3
BD009735C6	B022	SCSI 9GB 10K WU3
BD00975334	B915	SCSI 9GB 10K WU3
BD01862A67	B008	SCSI 18GB 10K WU3
BD0186349B	3B12	SCSI 18GB 10K WU3
BD018635C4	B022	SCSI 18GB 10K WU3
BD0186459A	B011	SCSI 18GB 10K WU3
BD01872A6A	B008	SCSI 18GB 10K WU3
BD018735C7	B022	SCSI 18GB 10K WU3
BD018745A3	B011	SCSI 18GB 10K WU3
BD036635C5	B022	SCSI 36GB 10K WU3
BD0366459B	B011	SCSI 36GB 10K WU3
BD036735C8	B022	SCSI 36GB 10K WU3
BD036745A4	B011	SCSI 36GB 10K WU3
BD03685A24	HPB4	SCSI 36GB 10K U320
BD03695A27	HPB4	SCSI 36GB 10K U320
BD0726459C	B011	SCSI 72GB 10K WU3
BD0728A4B4	HPB9	SCSI 72GB 10K U320
BD07285A25	HPB4	SCSI 72GB 10K U320
BD07287B4C	HPB9	SCSI 72GB 10K U320
BD0729A4B7	HPB9	SCSI 72GB 10K U320
BD07297B57	HPB9	SCSI 72GB 10K U320
BD1468A4B5	HPB9	SCSI 146GB 10K U320
BD14685A26	HPB4	SCSI 146GB 10K U320
BD14687B52	HPB9	SCSI 146GB 10K U320
BD1469A4B8	HPB9	SCSI 146GB 10K U320
BD14697B58	HPB9	SCSI 146GB 10K U320
BD3008A4B6	HPB9	SCSI 300GB 10K U320
BD30087B53	HPB9	SCSI 300GB 10K U320
BF01865222	B009	SCSI 18GB 15K WU3
BF01885A34	HPB4	SCSI 18GB 15K U320
BF03665223	B009	SCSI 36GB 15K WU3
BF0368A4B9	HPB5	SCSI 36GB 15K U320
BF03685A35	HPB4	SCSI 36GB 15K U320

**Smart Array 6i version 2.74 (continued from previous page)**

<b>Disk Drive Model</b>	<b>Minimum Firmware</b>	<b>Disk Drive Family</b>
BF03687B54	HPB5	SCSI 36GB 15K U320
BF0369A4BC	HPB5	SCSI 36GB 15K U320
BF03697B5A	HPB5	SCSI 36GB 15K U320
BF0728A4B4	HPB5	SCSI 72GB 15K U320
BF0728A4BA	HPB5	SCSI 72GB 15K U320
BF07285A36	HPB4	SCSI 72GB 15K U320
BF07287B55	HPB5	SCSI 72GB 15K U320
BF0729A4C2	HPB5	SCSI 72GB 15K U320
BF07297B5B	HPB5	SCSI 72GB 15K U320
BF1468A4BB	HPB5	SCSI 146GB 15K U320
BF14687B56	HPB5	SCSI 146GB 15K U320
BF1469A4C3	HPB5	SCSI 146GB 15K U320
BF14697B5C	HPB5	SCSI 146GB 15K U320