

Compaq ProLiant[®] ML370 Server Overview

Description

The ProLiant ML370 1GHz server contains the Pentium III processor. This new model includes all the features of the previous models.

New Models

The following table provides the part numbers and configuration codes for the updated ProLiant ML370:

Table 1: Part Numbers and Configuration Codes

Server Model	Part Number	Configuration Code
ProLiant ML370T01 P1000-256K 128MB	193689-001	FRY1
ProLiant ML370R01 P1000-256K 128MB	193691-001	FRZ1

New Features

This model brings the following changes to the ProLiant ML370 Pentium III line:

- 1GHz processor
- New PCI card Guide

Switch Settings

Table 2 lists the new SW1 settings for the 1.0GHz processor.

Table 2: SW1 Switch Settings

Switch Number	Positions			
	S2	S3	S4	S5
SW1	OFF	ON	OFF	OFF

New Options

Table 3 lists the new processor option kit available to upgrade previous models. The Pentium III 1GHz processor option kit is supported on all previously shipped and currently shipping ML370. Note that unlike the DL380 the ML370 will not require the Thermal Upgrade kit.

Table 3: Option Upgrade Kit

Description	Model	Part Number
Processor Option Kit	Pentium III P1000-256KB	187602-B21

Also available this announcement are Wide Ultra 3 hard drives listed in Table 4.

Table 4: Wide Ultra 3 Hard Drives

Description	Part Number
36.4GB NHP Wide Ultra3 SCSI 10,000 rpm Drive 1.6"	142676-B21
36.4GB NHP Wide Ultra3 SCSI 10,000 rpm Drive 1"	176497-B21
36.4GB HP Wide Ultra3 SCSI 10,000 rpm Drive 1"	176496-B22

New Spares

Table 5 lists spares kit associated with this processor.

Table 5: Spare Part Numbers

Description	Model	Part Number
1.0 GHz Processor	SPS-PROC,1GHZ/133 SECC2,B-0	221536-001
CPU Fan	SPS-FAN,SNGL SPD,120MM	212944-001
PCI Card Guide	PCI Card Guide	196627-001

OS Software Supported

For a complete and up-to-date listing of supported OSs and versions, visit the Compaq OS Support Matrix FTP site:

<ftp.compaq.com/pub/products/servers/os-support-matrix-310.pdf>

OS Drivers

For an up-to-date listing of the latest drivers available for the new 1-GHz models of the ProLiant ML370, visit the Compaq website:

www.compaq.com/support/files/server/us/index.html

New Versions of Required Utilities

SmartStart 4.9

New Installation/Repair Procedures

None

Service Considerations

None