HP ProLiant ML330 Generation 3 ATA C	ablin	estated	atrix	ATRA ATRA	THE BERT	4 4 4 6 6 6 4 6 6 6 4 6 6 6 6 6 6 6 6 6	Sei I I I I I I I I I I I I I I I I I I I	ALL ST	Land Contraction of the second	
Internal Cabling				<u> </u>						Кеу
ATA Hard Drive	$\checkmark$								~	Cable(s) included.
DAT and AIT Hot-Plug Tape Drives									C	Order option kit 273463-B21 - 2-device NHP SCSI cable.
DAT, AIT, DLT VS Tape Drives					0	0	0			
AIT 35-GB IDE Tape Drive		$\checkmark$								Drive Cage
External Cabling, Primary Storage										Not supported.
StorageWorks Enclosure 43XX Family			0	0	0	0	0		1	Order 5-m HD68-HD68 cable, part number 328215-001
External Cabling, Tape and Optical Storage									2	Order one of the following VHDCI-HD68 cables:
DAT, AIT, SDLT and 1/8 Autoloaders					✓	$\checkmark$	$\checkmark$			341177-B21—12-ft VHDCI-HD68 cable
DLT1 1280 SuperLoader					✓	$\checkmark$	$\checkmark$			341176-B21—6-ft VHDCI-HD68 cable
AIT, DAT, DLT, DLT VS, SDLT, and LTO Tape Drives					✓	$\checkmark$	$\checkmark$			201160-B21—10-m VHDCI-HD68 cable
3U Rackmount Kit (AIT, DAT, DLT, DLT VS, SDLT, LTO)					1	2	2		3	Order one of the following VHDCI-VHDCI cables:
5U Rackmount Kit (DLT, SDLT, LTO)					$\checkmark$	$\checkmark$	$\checkmark$			341175-B21—12-ft VHDCI-VHDCI cable
Smart Array Cluster Storage				$\checkmark$						341174-B21—6-ft VHDCI-VHDCI cable
External Cabling, Tape Libraries										Definitions
SSL2020 AIT Library						2				68—High-density 68-pin SCSI cable connector
MSL50XX and MSL60XX Libraries						3				<b>DCI</b> —Very high density cable interconnect 68-pin SCSI cable nnector
Internal Cable Part Numbers Cable Part Number (printed on cable)				Quan		Spare Numb	er		Pt.	<b>to pt</b> .—No termination on SCSI cable <b>D</b> —Low voltage differential supporting Wide Ultra2 transfer rates
235199-001 Internal ATA cable					1	25382	26-00	1		

NOTE: The information in this matrix lists whether or not additional cables need to be purchased with each controller-to-option configuration. For information on how to cable an option, refer to the HP ProLiant ML330 Generation 3 Setup and Installation Guide, the device-specific documentation, and the controller-specific documentation. For information on the specific options supported by the server, refer to the server and device QuickSpecs

© 2002, 2003 Hewlett-Packard Development Company, L.P.

Hewlett-Packard Company shall not be liable for technical or editorial errors or omissions contained herein. The information in this document is provided "as is" without warranty of any kind and is subject to change without notice. The warranties for HP products are set forth in the express limited warranty statements accompanying such products. Nothing herein should be construed as constituting an additional warranty.



Internal Cabling								
Wide Ultra320 Hot-Plug Hard Drives	$\checkmark$	$\checkmark$	$\checkmark$	$\checkmark$	$\checkmark$	$\checkmark$	÷	
Wide Ultra320 Universal Non-Hot Plug Hard Drives	$\checkmark$	>	>	>	>	>	÷	
DAT Non-Hot-Plug Tape Drives	0			0	0	0		
DAT and AIT Hot-Plug Tape Drives								
AIT 35-GB Tape Drive, LVD	$\checkmark$			0	0	0		
AIT 50-GB Tape Drive	~			0	0	0		
AIT 35-GB IDE Tape Drive								$\checkmark$
DLT VS Tape Drives	~			0	0	0		
External Cabling, Primary Storage								
StorageWorks Enclosure 43XX Family		$\checkmark$	$\checkmark$	$\checkmark$	$\checkmark$	$\checkmark$		
External Cabling, Tape and Optical Storage								
AIT, SSL1016, DAT, and 1/8 Autoloaders				>	>	>		
DLT1 1280 SuperLoader				$\checkmark$	$\checkmark$	$\checkmark$		
DAT, AIT, DLT, SDLT, and LTO Tape Drives				>	>	>		
DLT VS Tape Drives				2	>	>		
3U Rackmount Tape Drives (DAT, AIT, DLT, DLT VS, SDLT, LTO)				2	3	3		
5U Rackmount Tape Drives (DLT, SDLT, LTO)				>	>	>		
Smart Array Cluster Storage			$\checkmark$					
External Cabling, Tape Libraries								
SSL2020 AIT Library					1			
MSL50XX Libraries					4			

Кеу						
$\checkmark$	Cable(s) included.					
	Not supported.					
0	Order option kit 273463-B21 - 2-device NHP SCSI cable.					
	Order option kit 244059-B21, ML3xx Two Bay Hot Plug SCSI Drive Cage					
+	Refer to the RAID LC2 Controller User Guide for SCSI cabling and option kit information.					
1	Order one of the following VHDCI-HD68 cables:					
	341177-B21—12-ft VHDCI-HD68 cable					
	341176-B21—6-ft VHDCI-HD68 cable					
	201160-B21—10-m VHDCI-HD68 cable					
2	Order 5-m HD68-HD68 cable, part number 328215-001					
3	Order one of the following VHDCI-HD68 cables:					
	341177-B21—12-ft VHDCI-HD68 cable					
	341176-B21—6-ft VHDCI-HD68 cable					
	201160-B21—10-m VHDCI-HD68 cable					
4	Order one of the following VHDCI-VHDCI cables:					
	341175-B21—12-ft VHDCI-VHDCI cable					
	341174-B21—6-ft VHDCI-VHDCI cable					

## Definitions

HD68—High-density 68-pin SCSI cable connector

VHDCI-Very high density cable interconnect 68-pin SCSI cable connector

Pt. to pt.—No termination on SCSI cable

LVD—Low voltage differential supporting Wide Ultra2 transfer rates

Internal Cable Part Numbers								
Cable Part Number (printed on cable)	Cable Type	Quantity	Spare Kit Number					
148785-007	Internal SCSI Ultra3 5-device cable	1	289229-001					

**NOTE:** The information in this matrix lists whether or not additional cables need to be purchased with each controller-to-option configuration. For information on how to cable an option, refer to the *HP ProLiant ML330 Generation 3 Setup and Installation Guide*, the device-specific documentation, and the controller-specific documentation. For information on the specific options supported by the server, refer to the server and device QuickSpecs.

## © 2002, 2003 Hewlett-Packard Development Company, L.P.

Hewlett-Packard Company shall not be liable for technical or editorial errors or omissions contained herein. The information in this document is provided "as is" without warranty of any kind and is subject to change without notice. The warranties for HP products are set forth in the express limited warranty statements accompanying such products. Nothing herein should be construed as constituting an additional warranty.